


FUGITIVE OR SMOKE EMISSION INSPECTION
EPA METHOD 22 for OUTDOOR LOCATION

Company <u>Waste Management</u>	Observer <u>Mike McElvain</u>
Site <u>Cottonwood Hills</u>	Affiliation <u>WM</u>
Company Rep _____	Date <u>5.10.16</u>

Sky Conditions <u>P.C. 77°</u>	Wind Direction <u>South East</u>
Precipitation <u>None</u>	Wind Speed <u>5-10 mph</u>

Process Unit* <u>Open Flame</u>	Operational Status <u>On</u>
Current Monitoring Frequency <u>Quarterly</u>	
*(Flare, Solidification, Crusher, Diesel Engine)	

Sketch process unit. Indicate observer position relative to the source. Indicate potential emission points and/or actual emission points.



OBSERVATIONS

	Clock Time	Observation period duration (min:sec)	Accumulated emission time (min:sec)	
Begin Observation	<u>1000</u>			
	<u>1115</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1130</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1145</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1200</u>	<u>10 min</u>	<u>Ø</u>	
	<u>1215</u>	<u>10 min</u>	<u>Ø</u>	
	_____	<u>10 min</u>	<u>Ø</u>	
	_____	_____	_____	
End Observation	<u>1215</u>	<u>60 minutes</u>	<u>Ø</u>	Totals

Not applicable if checked:



© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

.....

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

Handwritten signature

Page 2